

AutomationDirect » Motor Starters

Part Number	Description	Coil Voltage	HP Rating		Motor Rating	Resistive Rating
			230V 3Ph	460V 3Ph	Amps	Amps
SC-E02G-24 VDC	Fuji Contactor	24 VDC	2	5	9	20
SC-E02-24 VAC	Fuji Contactor	24 VAC	2	5	9	20
SC-E02-110 VAC	Fuji Contactor	110 VAC	2	5	9	20
SC-E02-220 VAC	Fuji Contactor	220 VAC	2	5	9	20
SC-E03G-24 VDC	Fuji Contactor	24 VDC	3	7.5	12	20
SC-E03-110 VAC	Fuji Contactor	110 VAC	3	7.5	12	20
SC-E04G-24 VDC	Fuji Contactor	24 VDC	5	10	18	25
SC-E04-110 VAC	Fuji Contactor	110 VAC	5	10	18	25
SC-E05G-24 VDC	Fuji Contactor	24 VDC	7.5	10	18	25
SC-E05-110 VAC	Fuji Contactor	110 VAC	7.5	15	25	32
SZ-A11T	1NO + 1NC Front Mount Aux Contact					
SZ-AS1T	1NO + 1NC Side Mount Aux Contact					
SZ-RM	Reversing Mechanical Interlock					
SZ-ERW1A	Line side reversing connection kit					
SZ-ERW1D	Load side reversing connection kit					
SZ-Z1	Coil Surge Suppression 24-48V AC/DC					
SZ-Z2	Coil Surge Suppression 100-250V AC/DC					
TK-E02-145	Fuji Overload Relays			0.5	0.95 - 1.45	
TK-E02-220	Fuji Overload Relays			0.75	1.4 - 2.2	
TK-E02-260	Fuji Overload Relays		0.5	1	1.7 - 2.6	
TK-E02-340	Fuji Overload Relays				2.2 - 3.4	
TK-E02-420	Fuji Overload Relays		0.75	1.5 & 2	2.8 - 4.2	
TK-E02-600	Fuji Overload Relays		1	3	4.0 - 6.0	
TK-E02-800	Fuji Overload Relays		1.5		5.0 - 8.0	
TK-E02-900	Fuji Overload Relays		2	5	6.0 - 9.0	
TK-E02-1800	Fuji Overload Relays		5	10	12.0 - 18.0	
TK-E2-2600	Fuji Overload Relays		7.5	15	18-26	



Build a reversing starter with DUO line components

